



PATENT  
Docket No.: 77792/45

cgf

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

APPLICANT : Yasushi KUSAKA  
SERIAL NO. : 10/519,791  
FILED : 01 July 2003  
PATENT NO. : 7,098,624 B2 Issued 29 August 2006  
FOR : METHOD AND SYSTEM FOR DETECTING THE DISCONNECTION OF  
AN AUXILIARY POWER SUPPLY FROM A POLY-PHASE MOTOR

COMMISSIONER FOR PATENTS  
Customer Service Window  
Randolph Bldg.  
401 Dulany Street  
Alexandria, VA 22314

**REQUEST FOR CERTIFICATE OF CORRECTION**  
**PURSUANT TO 37 C.F.R. §1.322**

SIR:

Applicant hereby requests that the enclosed Certificate of Correction be issued for the above Patent under authority of 35 USC § 254.

The change represents correction of a typographical error which occurred during printing of the patent and was not the fault of the applicant. Specifically, claim 11, which was presented as claim 24 in the amendment filed 23 May 2006, was dependent upon claim 20. No fee is required.

Respectfully submitted,

Dated: 29 May 2007

Shawn W. O'Dowd  
(Reg. No. 34,687)

**Certificate**  
MAY 31 2007  
**of Correction**

KENYON & KENYON LLP  
1500 K Street, N.W., Suite 700  
Washington, D.C. 20005  
(202) 220-4200  
(202) 220-4201

MAY 31 2007

UNITED STATES PATENT AND TRADEMARK OFFICE

**CERTIFICATE OF CORRECTION**

**PATENT NO.** : 7,098,624 B2 Page 1 of 1  
**DATED** : 29 August 2006  
**INVENTOR(S)** : Yasushi KUSAKA

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<u>Column</u>	<u>Line</u>	
14	42	Change "claim 9" to --claim 20--.

**MAILING ADDRESS OF SENDER:**

Shawn W. O'Dowd  
KENYON & KENYON LLP  
1500 K Street, N.W., Suite 700  
Washington, DC 20005

Patent No.: 7,098,624 B2